

Fig. 1




Fig. 2




Fig. 3







Fig. 4





66d




Fig. 7

Applicant: LOWREY

Filed: Herewith

Attorney Docket No.: 0307091.0177

Sheet 8 of 10

66e

42a

Diagnostics

42b

Mapping

42c

Service Records

42d

Text Messaging

Found 12 service record(s). Click the Invoice Date or Work Order

Invoice Date	Work Order #	Company
11/10/03	209729	Honda of El Cerrito Service
08/22/03	202481	Honda of El Cerrito Service
08/21/03	199734	Honda of El Cerrito Service
03/15/03	189065	Honda of El Cerrito Service
02/03/03	185346	Honda of El Cerrito Service
11/06/02	177232	Honda of El Cerrito Service
09/06/02	171184	Honda of El Cerrito Service
07/09/02	165170	Honda of El Cerrito Service
06/17/02	161760	Honda of El Cerrito Service
04/30/02	158293	Honda of El Cerrito Service
03/28/02	155340	Honda of El Cerrito Service
03/22/02	154370	Honda of El Cerrito Service

Service Record

Work Order ID	209729
Invoice Date	11/09/03
Service Advisor Name & Number	PAUL FORTE (19)
Mileage	38143
Repair Cost	386.07

Job Information

Job Pay Type	Operation	Technician ID
1 Customer	01HOZ-37500 - 37500 MILE SERVICE	33
Comments: CUSTOMER REQUESTS 37,500 MILE SERVICE ESTIMATE INCLUDES HAZARDOUS WASTE CHARGE. RECOMMENDED MAINTENANCE : PERFORMED 37,500 MILE SERVICE		
2 Customer	30HOZ-FRZPOTR - FRONT PADS/ROTORS	33
Comments: NEEDS FRONT BRAKES : DUE TO NORMAL WEAR, REPLACED FRONT BRAKE PADS AND RESURFACED BOTH FRONT ROTORS		

Fig. 8




Fig. 9




Fig. 10